

Unit 1 Freemans Road
Portslade
BN41 1SL
Tel:0800 8496392

Warning

New vehicles with towbars fitted at the factory will have a 13 pin socket installed. If your caravan is pre 1999 the chances are that your caravan will not have a 13 pin plug. A 13 pin to 2 x 7 pin socket converter can be purchased (Part No:P7) but the fridge will not work. A Relay (part No:P32) should be installed in the caravan to activate the fridge.

Quick remedy

On the conversion lead (Part No P7) bridge pin 6 (fridge) to pin 2 (battery) on the 12S socket (this modification if the current is too high may cause overheating)



As viewed from the rear of the socket